

# IMPORTANT NOTICE

REGARDING THE FOLLOWING CABLETRON SYSTEMS PRODUCTS:

**FE-100TX, FE-100FX, and FE-100F3**

Under certain conditions it is possible for the **FE-100** uplink module to experience problems when used in the **SmartSwitch 2000** and **6000** family of products.

Known issues are specific to the **FE-100** units produced after **2/15/98**. These issues will be resolved by an upcoming release of firmware (Revision 4.01.10 or later) for the **SmartSwitch 2000** and **6000** products. For more information about this issue, please see Technical Bulletin TB0354-9, which is available on the Cabletron web site at:

<http://www.cabletron.com/support/techbltn/tb0354-9.html>

(Over)

P/N 9032666-02

To ensure full functionality of the **FE-100** when used with **SmartSwitch 2000** and **6000** products, it is recommended that the firmware be upgraded when the new firmware release becomes available.

To register for automatic notification via e-mail upon release of this firmware, please refer to the Cabletron Systems web site at:

<http://www.cabletron.com/support/FE100/>

For technical assistance with firmware upgrades, refer to your firmware release notes or contact the Cabletron Systems Global Call Center at (603) 332-9400.