

## CUSTOMER RELEASE NOTES

### ***Enterasys RoamAbout® Wireless Switch 8xx0 – Patch Release Firmware Version 6.0.4.6 November 7, 2007***

#### **INTRODUCTION:**

The RBT-8xx0 family of wireless switches includes the following: 1) the RBT-8100 and RBT-8110, which have the ability to control up to 24 access points; 2) the RBT-8200 and RBT-8210, which have the ability to control 24/48/72 access points; and 3) the RBT-8400, which has the ability to control 40/80/120 access points. The RoamAbout Switch Manager (RASM) can manage all of these devices.

The 6.0.4.6 Firmware Patch release addresses one customer escalation (refer to the [Firmware Changes and Enhancements](#) section).

**Enterasys recommends that you thoroughly review this document prior to installing or upgrading this product.**

**NOTICE: A Patch Release contains a small set of specific feature corrections which has not been subjected to the same standard of regression testing that a Generally Available Release would include. A Patch Release has been tested only to confirm that the specific feature set is functioning as expected. Unless otherwise stated in the Release Notes, a Patch Release has the same restrictions and limitations as the code upon which it was based. Please read *all* of the Release Notes pertaining to the Generally Available release prior to installation of any Patch in your production network. Please report any undocumented issues you find using the normal technical support procedures found in your product documentation.**

**NOTE: Please review the 6.0.4.4 RoamAbout Wireless Switch 8xx0 Release Notes for the full set of System Supported Items, Firmware Changes, and Known Restrictions.**

#### **FIRMWARE SPECIFICATION:**

| Status          | Version No. | Type  | Release Date  |
|-----------------|-------------|-------|---------------|
| Current Release | 6.0.4.6     | Patch | November 2007 |

#### **FIRMWARE CHANGES AND ENHANCEMENTS:**

Resolved an issue with high CPU loads on the RoamAbout Wireless Switches where an INFO message from the MP-422 Access Point appeared with every TKIP packet, causing the buffers to fill up quickly and the RBT switch to reset. The INFO message has been changed to a DEBUG message.

#### **KNOWN RESTRICTIONS AND LIMITATIONS:**

Please find the full list of Known Restrictions and Limitations in the 6.0.4.4 RoamAbout Wireless Switch 8xx0 Release Notes.

### GLOBAL SUPPORT:

By Phone: 978-684-1000  
1-800-872-8440 (toll-free in U.S. and Canada)

For the Enterasys Networks Support toll-free number in your country:  
<http://www.enterasys.com/support/>

By Email: [support@enterasys.com](mailto:support@enterasys.com)

By Web: <http://www.enterasys.com/support/>

By Fax: 978-684-1499

By Mail: Enterasys Networks, Inc.  
50 Minuteman Road  
Andover, MA 01810 (USA)

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Enterasys Networks Support web site.