

CUSTOMER RELEASE NOTES

RoamAbout MS-DOS and Windows 3.1 Driver Version 6.00.XX December 2000

INTRODUCTION:

The RoamAbout MS-DOS and Windows 3.1 driver allow you to install the RoamAbout driver using MS-DOS onto a Microsoft Windows 3.1 operating system to access the Network Interface Card (NIC).

It is recommended that this release note be thoroughly reviewed prior to the installation of this product.

SOFTWARE SPECIFICATION:

Status	Version No.	Type	Release Date
Current Version	6.00.XX	Customer/Software	12/01/00
Previous Version	4.00.XX	Customer/Software	11/14/99

HARDWARE COMPATIBILITY:

IEEE 802.11 RoamAbout PC Card, CSIBD-*, CSILD-*

BOOTPROM COMPATIBILITY:

N/A

NETWORK MANAGEMENT SOFTWARE SUPPORT:

N/A

SUPPORTED FUNCTIONALITY:

This driver is supported on the following operating systems:

- MS-DOS
- Microsoft Windows 3.1

And includes the following:

- Card Access driver for DOS, Version 1.04
- ODI driver for DOS, Version 6.00
- Packet driver for DOS, Version 6.00

INSTALLATION AND CONFIGURATION NOTES:

Perform the following to using MS-DOS to install the driver on a Windows 3.1 operating system:

1. Copy the software to a floppy diskette.
2. Run the batch file CPY2HRDSK.BAT with a chosen directory name.

Refer to the *RoamAbout 802.11 MS-DOS and Windows 3.1 Installation Guide*, DOS.pdf, for further installation and configuration information.

CUSTOMER RELEASE NOTES

CHANGES AND ENHANCEMENTS:

This release includes updated drivers.

KNOWN RESTRICTIONS AND LIMITATIONS:

- It is possible that you may run out of DOS memory when installing the new WVLANCAD.SYS driver. If you run into memory problems, and if the PC has Intel compatible 82365 PCMCIA controller, we recommend disabling Card and Socket Services.
- When using the Card Services, command line options are not necessary. It is possible to predefine resources for the driver to be used. Refer to *the RoamAbout 802.11 PC Card MS-DOS and Windows 3.1 Installation Guide, DOS.pdf*, for parameter information.

Any other problems than those listed above should be reported to our Technical Support Staff.

Y2K COMPLIANCE SUPPORT:

There's no "Real-Time Clock" in any of the RoamAbout products.

IETF STANDARDS MIB SUPPORT:

N/A

ROAMABOUT PRIVATE ENTERPRISE MIB SUPPORT:

N/A

SNMP TRAP SUPPORT:

N/A

ROAMABOUT PRIVATE ENTERPRISE TRAP SUPPORT:

N/A

GLOBAL SUPPORT:

By Phone: North America: (603) 332-9400	By Mail: Enterasys Networks, Inc.
Europe: 353 61 701 910	PO Box 5005
Asia: +800 8827-2878	35 Industrial Way
	Rochester, NH 03867-5005

For information regarding the latest firmware available, recent release note revisions, or if you require additional assistance, please visit the Enterasys Support web site or the Enterasys RoamAbout Wireless web site at <http://www.enterasys.com/wireless>.

Enterasys, Enterasys Networks, RoamAbout, and the RoamAbout logo are trademarks or registered trademarks of Cabletron Systems, Inc.

Microsoft and Windows are trademarks or registered trademarks of Microsoft Corporation. PC Card is a trademark of PCMCIA.

All other trademarks and registered trademarks are the property of their respective holders.