

CUSTOMER RELEASE NOTES

**RoamAbout® RBTSA-AA / RBTSA-AB Ethernet Adapter
Firmware Version 1.0.3
October 30, 2006**

Enterasys recommends that you thoroughly review this document prior to installing or upgrading this product.

FIRMWARE SPECIFICATION:

Status	Version No.	Type	Release Date
Current Version	1.0.3	Customer	10/30/06
Previous Version	1.0.1	Customer	1/20/06
Initial Release	1.0.0	Customer	6/25/05

INSTALLATION AND CONFIGURATION NOTES:

Refer to the *RoamAbout Wireless Ethernet Adapter Quick Start* and the *RoamAbout Wireless Ethernet Adapter User Guide*, located on the CD-ROM provided in the original shipping container, for installation and configuration information.

To ensure that you have the latest documentation, go to <http://www.enterasys.com/products/wireless>.

FIRMWARE CHANGES AND ENHANCEMENTS:

V1.0.3

Fixed a problem where the A radio was missing for the country code ES.

V1.0.1

Fixed a problem where the ARP cache was filling up and not allowing for new entries to be added and at times dropping existing connections.

KNOWN RESTRICTIONS AND LIMITATIONS:

There are no known issues.

GLOBAL SUPPORT:

By Phone: 978-684-1000
1-800-872-8440 (toll-free in U.S. and Canada)

For the Enterasys Networks Support toll-free number in your country:
<http://www.enterasys.com/services/support/contact/>

By Email: support@enterasys.com

By Web: <http://www.enterasys.com/services/support/>

By Fax: 978-684-1499

By Mail: Enterasys Networks, Inc.
50 Minuteman Road
Andover, MA 01810 (USA)

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Enterasys Networks Support web site.